## CITY OF SAN ANTONIO

## POADP APPLICATION

The platting of property in two or more subdivision units requires the submission of a Preliminary Overall Development Plan, POADP. To be accepted for review a POADP shall comply with the provisions of ARTICLE II, Division 2 Preliminary Overall Development Plans of the San Antonio Unified Development Code and must be certified to contain the following:

Date Submitted: 6/16/98	Name of POADP: DAVENPORT 207
Owners: DUGAS DIVERSIFIED	Consulting Firm: W.F. CASTELLA & ASSOC
Address: 14502 BROOK HOLLO	W Address: 1039 W. HILDEBRAND
SAN ANTONIO TX 7812	232 SAN ANTONIO TX 7820
Phone: (210) 402 0866	Phone: 7345351
Existing zoning: R5 & B2	Proposed zoning:
Site is over/within/includes:  Edwards Aquifer Recorded # of Phases San Antonio City Lin Council District: Ferguson map grid	:: UNK. Yes   No Phase
Land area being platted: Lots	Acres
Single Family (SF)  Multi-family (MF)  Commercial and non-residential	
Is there a previous POADP for this Site? Name	
Is there a corresponding PUD for this site? Name	
Plats associated with this POADP or site? Name	No.   SER   E   E   E   E   E   E   E   E   E
Name	No
Name	No
Contact Person and authorized representative:  Print Name: STEVEN E. HANAN Sign	nature leva & Hanan
Print Name: <u>STEVEN E. HANAN</u> Sign  Date: <u>6/15/98</u> Phone:	734 535 / Fax:

Û	name of the POADP and the subdivision; (SUBDIVISION NAME NOT KNOWN)
	indication of development phases on the POADP; NOT KNOWN AT THIS TIME
回	perimeter property lines of the POADP (in a line weight and character distinguishable from other lines);
d	north arrow and scale of the map;
	proposed land use by location, type and acreage;
卤	delineation of the circulation system including all collectors, arterial, and local type "B" streets;
	contour lines at intervals no greater than ten (10) feet;
	legal recorded ownership of adjacent properties and if known proposed development of adjacent unimproved properties;
	existing adjacent or perimeter streets;
Ø	one hundred year flood plain limits;
Ø	location map indicating location and distance of the POADP to adjacent streets and at least two (2) major thoroughfares.
ď	a complete application and certification with six copies of the POADP map, all maps to be folded (accordion style & manageable size);
/A 🗆	POADP amendments or revisions must be graphically indicated and include a concise statement describing said amendment or revision on the POADP map;
	TIA requirements must be met prior to acceptance of a POADP, contact Amer Galani @ (210)207-2076;  PREVIOUSLY APPROVED WY ZONING CASE Z 97259
	Tree preservation requirements must be met prior to acceptance of a POADP, contact Debbie Reid @207-7102;
d	the POADP does does not abut State Highway Department facilities and one additional copy of the POADP plan has been submitted directly to TXDOT for their review. Contact Judy Friesenhahen @ (210) 615-5814;
Ø	The POADP is is is not located over the Edwards Aquifer recharge zone and one additional copy of the POADP has been submitted directly to the Aquifer Studies office of San Antonio Water Systems, contact Kirk Nixon (210) 704-7392;
	certify that the POADP application and accompanying maps are complete and that the conditions listed on this plication have been met.
	ertifying Representative:
Pr	int Name: STEVEN HANAN Signature: Steva C. Javan
If	you have any questions please call Elizabeth Carol at 207-7900



## OF SAN ANTONIO

October 2, 1998

Steven E. Hanan W. F. Castella & Assoc. 1039 W. Hildebrand San Antonio, TX 78201

Re: Davenport 207

POADP # 614

Dear Mr. Hanan:

The City Staff Development Review Committee has reviewed Davenport 207 Subdivision Preliminary Overall Area Development Plan # 614. Please find enclosed a signed copy for your files. Although your plan was accepted, please note the following:

- Based on the topography, a Flood Plain Study and drainage review will probably be required during the platting process.
- · Access and R.O.W. issues along State facilities will need to be resolved with the Texas Department of Transportation (TXDOT). For information about these requirements you can contact TXDOT at 615-5814.
- This development will need to comply with tree preservation ordinance #85262. For information about these requirements you can contact Building Inspections at 207-7102.
- It will be expected that you will plat all of the property depicted in your POADP, to include: floodpains, drainage areas and open space.
- I would encourage you to work closely with the school district, so that they can plan accordingly.

Please note that this action by the committee does not establish any commitment for the provision of utilities, services or zoning of any type now or in the future by the City of San Antonio. If the proposed development is not platted in phases this POADP will be invalid. Platting will have to comply with the UDC.

If you have any questions or comments regarding this matter, please contact Ms. Elizabeth Carol, at (210) 207-7900.

Sincerely,

Emil R. Moneivais AIA, AICP

Director of Planning

EM/EAC

cc: Andrew J. Ballard, P. E., City Engineer

TXDOT TRANS PLANNING Fax:2106156295

Texas Departmen

Jun 18 '98 10:16 P.01

To Elizabeth Caro I From JC454 Hases

Co. The Phone # Phone # 6/5 5860

Fax# 207 4441 Fax#

P.O. BOX 29928 . SAN ANTONIC

June 17, 1998

## P.O.A.D.P. REVIEW

Davenport 207

Located on F.M. 78 at Old Foster Road

P.O.A.D.P. Reviewed for:

Comments

Noise Mitigation

For residential development directly adjacent to State ROW, the developer shall be responsible for adequate set-back and/or sound abatement.

R.O.W. Requirements

50' ROW flares will be required at the intersection of the planned

collector street and FM 78.

Access Limits/Restrictions

Locations of access points will be as directed by "Regulations For Access Driveways to State Highways". This development is eligible for a maximum combined total of four access points.

WPAP Requirements

None.

Permit applications along with plans for street, driveway, utility, sidewalk and drainage construction must be submitted to the Texas Department of Transportation for review and approval before working on highway ROW. TxDOT requires that a recorded plat accompany all driveway permit applications. The Owner/Developer is responsible for preventing any adverse impact to the existing drainage system within highway ROW.

ADDITIONAL COMMENTS:

Judy Friesenhahn, P.E. Advanced Project

ridy Trisinlator

Development Engineer



W.F. CASTELLA & ASSOCIATES, NC. Engineers • Surveyors • Planners

CITY OF SAN ANTONIO ATTN: ELIZABETH CAROLL JUNE 26, 1998

RE: DAVENPORT 207 POADP

ELIZABETH,

ACCORDING TO OUR PHONE CONVERSATION TODAY THE FOLLOWING ISSUES ARE RAISED REGARDING ABOVE POADP:

- 1) THE APPROXIMATE NUMBER OF PHASES IS DESIRED
- 2) THE APPROXIMATE NUMBER OF COMMERCIAL LOTS IS DESIRED.
- 3) OLD FOSTER NEEDS TO BE INDATED "CLOSED" PER BEXAR COUNTY.
- 4) REROUTE COLLECTOR STREET TO DISCOURAGE THRU-TRAFFIC IS REQUESTED.
- 5) LOCATION OF LOCAL STREET INTERSECTIONS OFF COLLECTOR IS REQUESTED.

IF THIS ACCURATELY REFLECTS YOUR NOTES COULD YOU FAX ME A NOTE TO THAT EFFECT.

YOUR ATTENTION IS APPRECATED.

W.F. CASTELLA & ASSOCIATES

LEE WRIGHT

SUBDIVISION COORDINATOR

6004) 622.98

TRANSMISSION OK

TX/RX NO.

7734

CONNECTION TEL

97345363

CONNECTION ID

START TIME

06/29 14:45

USAGE TIME

01'13

PAGES

2

RESULT

OK

REMIT TO: CITY OF SAN ANTONIO P.O. BOX 839975 SAN ANTONIO, TX 78283-3975

INVOICE 1208837

AMT ENCLOSED \_

AMOUNT DUE INVOICE DATE 6/26/1998 DUE DATE 6/26/1998

370.00

50-04-5573 DUGAS DIVERSIFIED DEVELOPMENTS 14502 BROOK HOLLOW S.A. TX 78232

\_\_\_\_\_\_\_ PHONE: 000 - 0000

POADP

DAVENPORT 207

FACILITY LOCATION: 100 COMMERCE ST W 

INVOICE DATE INVOICE ACCOUNT DUE DATE OFFICE HOURS 6/26/1998 1208837 50-04-5573 6/26/1998 7:45 - 4:30

LINE INDEX REF DESCRIPTION 1 012542-001 PLAN REVIEW FEES

AMOUNT 370.00

PAID SATO JUN 2 6 1988 MP-R

AGREEMENT DATES SERVICE DATES ORDINANCE CONTRACT DOCUMENT O6/25/1998 CK# 1017 DAVENPORT 207

06/25/1998

PREVIOUS BAL CURRENT CHARGES NEW BALANCE TOTAL AMT DUE 370.00 370.00

CITY OF SAN ANTONIO
PLANNING-FOURTH FLOOR P.O. BOX 839975 SAN ANTONIO, TX 78283-3975 PAGE 1 OF 1

paver port au Near Faste + Segin en courages extern projutoraffic - from Lakevien Projutor · tree , TX DOT · remove DID Foster dosa remove if it dos not exist. . off-sot the collector Street and there E Street and Lake view drive 6 reconsider of amore Escious routing of the collector streeto to discorrage the traffic.

Daven port -revised @ Foster + Seguin 900 SFlots on 139 aces 68 acres for comme 4/10-20 phases remark the notes

- TIA - Foster needs 86'

cellee 9.21.98

on Foster Rd. indicets 3brig senetopment Which planning staff Mill not support as

FOR DOVERPORT



Doverport traffic circle verify traffic circle

Since it is in the City.

is O.K.